



Confined Space/ Register

Definition

A 'confined space' means an enclosed or partially enclosed space that:

- is not designed or intended to be occupied by a person
- is, or is designed or intended to be, at normal atmospheric pressure while any person is in the space; and
- is or is likely to be a risk to health and safety from:
 - an atmosphere that does not have a safe oxygen level, or
 - contaminants, including airborne gases, vapours and dusts, that may cause injury from fire or explosion, or
 - harmful concentrations of any airborne contaminants, or engulfment

This Confined Space register provides information on:

- Location of confined space
- Photo identification

Note: This is not a risk assessment. Persons accessing the Confined Space must conduct a risk assessment and SWMS/JSA relevant to the task they are undertaking prior to entering the confined space.

Work permit with SWMS required for entry into confined space







Where pits need to be emptied University of Adelaide strongly recommends the use of the vacuum system.

This Register excludes 3rd party asset owners pits e.g. SA Water, SAPN and Telstra

Campus':

North Terrace
Thebarton









At time of distribution the University of Adelaide has identified all known Confined Spaces. If you are aware or become aware of any confined spaces not identified in this document, can you please email the details to facilitiesupport@adelaide.edu.au

Name of Building/Area	Building Number/Map reference	Location - Description	Nature of the space	Photo	Signed	Permission to work	Key Required from Security
Benham Laboratories	D10	M Toilet room 111, F Toilet room 124	Roof Void		Yes	UoA	Yes
Benham Laboratories	D10	C9-3 South West corner in grass	Pit - Neutraliser		Yes	UoA	No
Benham Laboratories	D10	C9-2 South east corner in grass	Pit - Neutraliser		Yes	UoA	No
Benham Laboratories	D10	C9-5 South west corner in grass	Pit - Stormwater Ejector		Yes	UoA	No
Benham Laboratories	D10	North western corner of building near gate 9	Pit - Stormwater		No	UoA	No
Bonython Hall	M3	Auditorium last two rows	Under floor cavity		No	UoA	No









Warning	This process is uncontrolled when printed. The current version is available on the I&TS Website.	Effective	September 2023	Version:	2.0
Authorised by	Director, Capital Projects & Facilities Management Infrastructure Branch Division of University	Review	September 2026	Page: 2 of 12	
Filepath	S:\Services_Resources\Infrastructure\Shared\HSW\01. Hazard Management\07 Confined Spaces\Confined Spaces Register North Terrace September 2023.docx				

Darling Building	G8	In corridor 211F	Roof Void		Yes	UoA	Yes
Darling Building	G8	G6-12A Courtyard east	Pit - Neutraliser		No	UoA	No
Darling Building	G8	G6-16 Courtyard west	Pit - Neutraliser		No	UoA	No
Darling Building	G8	G6-5 North east corner	Pit - Neutraliser		Yes	UoA	No
Darling Building	G8	G6-9 South east corner	Pit - Neutraliser		No	UoA	No
Darling Building	G8	G6-9 East corner	Pit - Neutraliser		Yes	UoA	No
Darling Building	G8	G6-12 Courtyard east	Pit - Neutraliser		No	UoA	No

Warning	This process is uncontrolled when printed. The current version is available on the I&TS Website.	Effective	September 2023	Version:	2.0
Authorised by	Director, Capital Projects & Facilities Management Infrastructure Branch Division of University	Review	September 2026	Page: 3 of 12	
Filepath	S:\Services_Resources\Infrastructure\Shared\HSW\01. Hazard Management\07 Confined Spaces\Confined Spaces Register North Terrace September 2023.docx				

Engineering Annex A Building	G15	F13-2, Southern ext in garden	Pit - Neutraliser		Yes	UoA	No
Engineering North Building	G14	F11-4, South east corner	Pit - Neutraliser		No	UoA	No
Engineering North Building	G14	East end in garden bed, near boundary fence	Pit - Stormwater		No	UoA	No
Engineering North Building (Flume)	G14	Lower Ground floor workshop	Underfloor water storage		Yes	UoA	Yes
Engineering North Building (Flume)	G14	Upper Ground floor workshop	Entry to Volume Measurement Entry Tank		Yes	UoA	Yes
Engineering North Building (Flume)	G14	Upper Ground floor workshop	30 foot flume		Yes	UoA	Yes
Engineering North Building (Flume)	G14	Upper Ground floor workshop	Low Head Overhead Tank		Yes	UoA	Yes
George Murray Building	D8	North end near gate 9, In roadway near boundary fence	Pit - Stormwater		No	UoA	No








Warning	This process is uncontrolled when printed. The current version is available on the I&TS Website.	Effective	September 2023	Version:	2.0
Authorised by	Director, Capital Projects & Facilities Management Infrastructure Branch Division of University	Review	September 2026	Page: 4 of 12	
Filepath	S:\Services_Resources\Infrastructure\Shared\HSW\01. Hazard Management\07 Confined Spaces\Confined Spaces Register North Terrace September 2023.docx				

Badger Building	E5	D3 -2 North side in pavement at entrance	Pit - Neutraliser		Yes	UoA	No
Badger Building	E5	D3-1, north west corner in garden	Pit - Neutraliser		Yes	UoA	No
Hughes Building	K10	J8-1, External Pump point, Plant room 104A	Pit - Sewage Ejector		Yes	UoA	No
Johnson Building	C4	C2-1, west end of garden	Pit - Neutraliser		No	UoA	No
Johnson Building	C4	C2-2, north east corner in grass	Pit - Neutraliser		No	UoA	No
Johnson Building	C4	C2-3, Courtyard in garden	Pit - Neutraliser		No	UoA	No
Johnson Building	C4	Roof space, west end, access from room 303 (Level 3)	Roof Void		No	UoA	Yes
Johnson Building	C4	Roof space, east side, via Plant room 122B (Level 1)	Roof Void		No	UoA	Yes

Warning	This process is uncontrolled when printed. The current version is available on the I&TS Website.		Effective	September 2023	Version:	2.0
Authorised by	Director, Capital Projects & Facilities Management Infrastructure Branch Division of University	Review	September 2026			
Filepath	S:\Services_Resources\Infrastructure\Shared\HSW\01. Hazard Management\07 Confined Spaces\Confined Spaces Register North Terrace September 2023.docx					

Johnson Building	C4	C1-1, South east corner in garden	Pit - Neutraliser		No	UoA	No
Jordan Laboratories	D3	Room G07W, in floor	Storage tank		No	UoA	Yes
Ligertwood Building	M15	L13-1, Plant Room LG02A	Pit - Sullage Ejector		No	UoA	Yes
Mawson Laboratories	B12	B11-3, south side east end	Pit - Neutraliser		No	UoA	No
Mawson Laboratories	B12	B11-4, south side east end	Pit - Neutraliser		No	UoA	No
Mawson Laboratories	B12	B11-5, Courtyard east end paving	Pit - Sewage Ejector		No	UoA	No
Mawson Laboratories	B12	In corridor 101, Outside room 126 and in room 127	Roof Void			UoA	Yes
Mawson Laboratories	B12	Northern side of building, in paved section near boundary	Pit - Stormwater		Yes	UoA	No
Mawson Laboratories	B12	North eastern corner, grounds near boundary Victoria Drive and Frome Road	Pit - Stormwater		Yes	UoA	No








Warning	This process is uncontrolled when printed. The current version is available on the I&TS Website.	Effective	September 2023	Version:	2.0
Authorised by	Director, Capital Projects & Facilities Management Infrastructure Branch Division of University	Review	September 2026	Page: 6 of 12	
Filepath	S:\Services_Resources\Infrastructure\Shared\HSW\01. Hazard Management\07 Confined Spaces\Confined Spaces Register North Terrace September 2023.docx				

Helen Mayo North Building	D17	C15-2, Basement plant room NB34	Pit - Sewage Ejector		Yes	UoA	Yes
Helen Mayo North Building	D17	C15-3, North east corner in road	Pit - Neutraliser		Yes	UoA	No
Helen Mayo North Building	D17	C15-4, South west end in ramp	Pit - Stormwater Ejector		No	UoA	No
Helen Mayo North Building	D17	C15-5, Basement plant room NB 34	Pit - Sullage Ejector		Yes	UoA	Yes
Helen Mayo North Building	D17	North eastern end of building near southern corner, in roadway	Pit - Stormwater		No	UoA	No
Helen Mayo North Building	D17	North eastern end of building, northern corner, in roadway	Pit - Stormwater		No	UoA	No
Helen Mayo South Building	E17	D15-2, East end in road	Pit - Neutraliser		Yes	UoA	No







Warning	This process is uncontrolled when printed. The current version is available on the I&TS Website.	Effective	September 2023	Version:	2.0
Authorised by	Director, Capital Projects & Facilities Management Infrastructure Branch Division of University	Review	September 2026	Page: 7 of 12	
Filepath	S:\Services_Resources\Infrastructure\Shared\HSW\01. Hazard Management\07 Confined Spaces\Confined Spaces Register North Terrace September 2023.docx				

Helen Mayo South Building	E17	D15-3, South side, east end in road	Pit - Neutraliser		No	UoA	No
Helen Mayo South Building	E17	D15-4, South side, west end in pavement	Pit - Neutraliser		Yes	UoA	No
Helen Mayo South Building	E17	On Roof, via doorway on roof top	Roof Void		Yes	UoA	Yes
Helen Mayo South Building	E17	In cement before entrance right side	Pit - Neutraliser		No	UoA	No
Helen Mayo South Building	E17	D15-1, North side, east end in paving	Pit - Neutraliser		No	UoA	No
Mitchell Building	M10	Below Ground Level, access via room G02A	Under Floor Cavity		No	UoA	No
Molecular Life Sciences	C13	C11-1, North west corner in paving	Pit - Neutraliser		Yes	UoA	No



Warning	This process is uncontrolled when printed. The current version is available on the I&TS Website.	Effective	September 2023	Version:	2.0
Authorised by	Director, Capital Projects & Facilities Management Infrastructure Branch Division of University	Review	September 2026	Page: 8 of 12	
Filepath	S:\Services_Resources\Infrastructure\Shared\HSW\01. Hazard Management\07 Confined Spaces\Confined Spaces Register North Terrace September 2023.docx				

Molecular Life Sciences	C13	C11-2, east end in paving	Pit - Neutraliser		Yes	UoA	No
Napier Building - Lower	L14	K12-1, Plant Room LG25C	Pit - Sullage Ejector		Yes	UoA	Yes
Napier Building - Lower	L14	K12-2, Plant Room LG25C	Pit - Sullage Ejector		Yes	UoA	Yes
Napier Building - Lower	L14	East side behind Female Toilets LG30A, via east c	Service Ducts		Yes	UoA	Yes
Napier Building - Lower	L14	Behind Men's Toilet, down stairwell LG25, off west corridor LG01L, door LG25A	Service Ducts		Yes	UoA	Yes
Napier Building - Lower	L14	Northern lawn area, Lower Ground	Storm Water		No	UoA	No
Napier Building - Tower	L14	Ground Floor Lecture Theatre, North East side, LL carpark	Service Ducts		No	UoA	Yes




Warning	This process is uncontrolled when printed. The current version is available on the I&TS Website.	Effective	September 2023	Version:	2.0
Authorised by	Director, Capital Projects & Facilities Management Infrastructure Branch Division of University	Review	September 2026	Page: 9 of 12	
Filepath	S:\Services_Resources\Infrastructure\Shared\HSW\01. Hazard Management\07 Confined Spaces\Confined Spaces Register North Terrace September 2023.docx				

Oliphant Building	J6	H4-1, north side in garden	Pit - Neutraliser		Yes	UoA	No
Oliphant Building	J6	Room G10, In pump room G11	Pit		Unable to access	UoA	
Oliphant Building	J6	Garden area south east corner, opposite G17A Maintenance Service Centre	Well		No	UoA	No
Oliphant Building	J6	In corridor G01C, 4 hatches in floor, all the same	Under Floor Cavity		Yes	UoA	No
Physics Building	H7	Top of Stairs - Door 201, corridor 101 ceiling, near room 129	Roof Void		Yes	UoA	No
Physics Building	H7	Rm B02 below G41, Rm G03 near G10C, Corridor G03g near Rm G18 and Rm G23	Under Floor Cavity		Yes	UoA	No
Schulz Building	H4	Basement ceiling, in plant room B5, hatch above ceiling tile	Ceiling Space		Yes	UoA	No
Union House	F7	E5-1, Little Theatre, room 116	Pit - Sewage Ejector		Currently construction site	UoA	
Union House	F7	E5-2, Kitchen under stairs	Pit - Grease Arrestor		Currently construction site	UoA	

Warning	This process is uncontrolled when printed. The current version is available on the I&TS Website.	Effective	September 2023	Version:	2.0
Authorised by	Director, Capital Projects & Facilities Management Infrastructure Branch Division of University	Review	September 2026	Page: 10 of 12	
Filepath	S:\Services_Resources\Infrastructure\Shared\HSW\01. Hazard Management\07 Confined Spaces\Confined Spaces Register North Terrace September 2023.docx				

Union House	F7	Level 2 Room 214B, northern wall	Service Ducts		Currently construction site	UoA	
Kenneth Wills Building	L10	East side of pond in garden, cover in ground	Pump Room		Yes	UoA	No
Maths Lawns -East	L14	In lawn North East side	Stormwater retention tanks		No	UoA	No

Warning	This process is uncontrolled when printed. The current version is available on the I&TS Website.		Effective	September 2023	Version:	2.0
Authorised by	Director, Capital Projects & Facilities Management Infrastructure Branch Division of University		Review	September 2026	Page: 11 of 12	
Filepath	S:\Services_Resources\Infrastructure\Shared\HSW\01. Hazard Management\07 Confined Spaces\Confined Spaces Register North Terrace September 2023.docx					

Name of Building/Area	Building Number/Map reference	Location Description	Nature of the space	Photo	Signed	Permission to Work	Key Required from Security
National Wine Centre Plant Room	3	Floor	Pit		Yes	UoA	Yes
Yarrabee House		Entrance Hall 0.13 Ground level	Under Floor Cavity		Yes	UoA	No
Thebarton Campus (The Ranch courtyard)		Directly adjacent old basketball court	Underground tunnel		No	UoA	Yes

Warning	This process is uncontrolled when printed. The current version is available on the I&TS Website.		Effective	September 2023	Version:	2.0
Authorised by	Director, Capital Projects & Facilities Management Infrastructure Branch Division of University		Review	September 2026	Page: 12 of 12	
Filepath	S:\Services_Resources\Infrastructure\Shared\HSW\01. Hazard Management\07 Confined Spaces\Confined Spaces Register North Terrace September 2023.docx					